

# Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 3/29/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 3/29/2022

## Inspection Photos



**Photo 1.** Facing southwest along the main road near the well site. Stormwater has washed across the road causing erosion. The culvert is filled in with sediment and has not been repaired. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 3/29/2022

## Inspection Photos



**Photo 2.** The culvert outlet is eroded and has not been repaired. No culvert outlet protection installed. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 3/29/2022

## Inspection Photos



**Photo 3.** Facing toward the northeast side of the location. This area is not stabilized and there is an erosion. The wattles are degraded shown at red arrow. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 3/29/2022

## Inspection Photos



**Photo 4.** Facing toward the northeast side of the location. This area is not stabilized and there is an erosion channel that will need to be repaired. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 3/29/2022