

Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 3/29/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 1. Facing southeast along the main road at the upper part of Lorencito Canyon. There is erosion along the road from recent storm event. Stormwater is bypassing the culvert. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 2. The culvert along the road is filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00581,-104.83861. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 2. The culvert along the road is filled in with sediment causing stormwater to flow down the side of the road. Lat/Long:37.00499,-104.83742. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 3. The road along the canyon is not stabilized and there is rutting and vehicle tracking occurring. The road needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 5. The side of the road is eroded and is not stabilized at Lat/Long:36.99952,-104.83425. This area or erosion needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 6. The side of the road is eroded and not stabilized at Lat/Long:36.99952,-104.83425. Erosion head cutting is continuing to occur further back. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 7. There was grading performed along the road. The disturbance along the side of the road shown at red arrow needs to be seeded and reclaimed. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 8. The culvert along the road is filled in with sediment at Lat/Long:36.99405,-104.84710.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022

Inspection Photos



Photo 9. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/29/2022