

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2022

Submitted Date:

03/30/2022

Document Number:

699602995

FIELD INSPECTION FORM

Loc ID 323561 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245404	WELL	SI	02/01/2017	GW	123-13199	PRINTZ 2-31	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Kill well | WK.
Battery: Inactive | Shut-down.
Inactive Battery SE corner GPS coordinates: 40.448170,-104.590900

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Plunger Lift	# 0			
Comment:	Plugging Operations: Equipment removed.			
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 245404 Type: WELL API Number: 123-13199 Status: SI Insp. Status: PA

BradenHead

Date of Last Brhd Test: 05/13/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Workover

Comment: [Workover Contractor: A-Plus. Rig #10.](#)

[Reference:](#)
[Form 6N on file. Notice of Intent to Abandon date: 03/07/2022. Approved.](#)

[Form 42 on file. Notice of MIRU.](#)
[Start Date: 03/28/2022. Approved.](#)

[Form 42 on file. Notice of Plugging Operations.](#)
[Start Date: 03/28/2022. Approved.](#)

[Kill well to prep for PA. Use portable flare to vent gas.](#)

[TP-950 PSI, CP-900 PSI, SCP-0 PSI, ROAD RIG AND EQUIPMENT TO LOCATION, HELD SAFETY MEETING WITH RIG CREW, TRUCK DRIVERS, AND SELECT ENERGY FLOW BACK CREW, SPOT IN AND RIG UP PULLING UNIT, RIG EQUIPMENT AND FLOW BACK IRON, PRES TEST LINES AND START FLARING GAS, PRES TEST BOP, GOT PRESSURE DOWN TO 600 PSI, CONTROL WELL WITH 150 BBLS OF FRESH WATER, RD FLOW BACK CREW, N/D TREE, N/U BOP AND TBC EQUIPMENT, PRES/TEST PIPE RAMS, STAND BACK 112 JTS AND LD REST OF TBG ON TRAILER, SECURE WELL, WINTERIZE EQUIPMENT, SDFN.](#)

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 02/29/2022 at approximately 13:06 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: PRINTZ-66N64W /31NWNE Location ID: 323561 Well Name(s): Printz 2-31. API: 05-123-13199. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Kill well WK. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.448170,-104.590900</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602996	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709288