

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #6312 from entrance to location.



Photo #6313 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #6314 Rill erosion occurring in ditch.



Photo #6315 Rill erosion occurring in ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #6316 Rill erosion occurring in ditch.



Photo #6317 Insufficient velocity checks in ditch.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #6318 Sediment is encroaching on vegetation.



Photo #6319 Sediment chocking off vegetation.