

TEP  
KP 23-17  
Location # 335208



location



location

TEP  
KP 23-17  
Location # 335208



location



Tank signage is illegible



TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/compaction/ degradation**



**Lack of stabilization/compaction/ degradation**





TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/compaction/ degradation**



**Lack of stabilization/compaction/ degradation**



TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/erosion**



**Lack of stabilization/erosion**



TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/erosion**



**Lack of stabilization/erosion**



TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/erosion**



**Lack of stabilization/erosion**



TEP  
KP 23-17  
Location # 335208



**Lack of stabilization/erosion**



**Lack of stabilization/erosion**





TEP  
KP 23-17  
Location # 335208



**Missing cap/plug**



**Chemical tank containment full of fluid**





TEP  
KP 23-17  
Location # 335208



**Main access road lack of stabilization**

