

Inspection Photos
Location Name: A21-13 /Pad
Location #: 449369



Photo #1

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770** Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Frac: Halliburton crew, NE corner



Photo #2

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770** Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Frac: Halliburton crew, NW corner

Inspection Photos
Location Name: A21-13 /Pad
Location #: 449369



Photo #3

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770**

Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Diesel tanks: Grounded



Photo #4

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770**

Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Flow tanks: Grounded

Inspection Photos
Location Name: A21-13 /Pad
Location #: 449369



Photo #5

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770**
Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Site entrance: signage



Photo #6

**Rampart A33-730, A33-740, A33-750, A33-760,
A33-770**
Wellsite

Waiting on Completion | WO

Frac Operations: Active; Rampart A33-730, A33-750

Site entrance: Safety signage