

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
Comment:	Dead weeds around ancillary equipment		
Corrective Action:	Comply with Rule 606	Date:	02/07/2022

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Ancillary equipment		# 1		
Comment:	electric panel, meter box and transformers			
Corrective Action:			Date:	
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:			Date:	
Pump Jack		# 1		
Comment:				
Corrective Action:			Date:	
Bradenhead		# 1		
Comment:	appears plumbed to surface			
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241290 Type: WELL API Number: 123-09078 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/26/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 3/28/2022 at approximately 1450 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Location: Mahoney 2 API #05-123-09078 County: Weld. While there, I observed a wellsite, PR at the time of inspection. During this inspection the following possible compliance issue was observed and is now delinquent: 606 houskeeping: Dead Weeds around ancillary equip. CA Date 2-7-2022. During this inspection the following possible compliance issues have been cleared: 419.a.(1),(2) Bradenhead access: Bradenhead is accessible initial inspection the access was covered with dirt and not visible. 419.b.(5) Bradenhead Monthly Reporting: bradenhead appears to be plumbed to surface for testing. Location: Dry, Weather: cloudy. A follow up on this site inspection needs to be conducted. Compliance issues appear to have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	03/28/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402997012	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706223
702400131	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706220