

Inspection Photos
Operator Name: Caerus
Location ID: 334942



Existing sales flowline was abandoned and removed from location

Inspection Photos
Operator Name: Caerus
Location ID: 334942



Appears to be external corrosion