

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/17/2022

Submitted Date:

04/04/2022

Document Number:

693200994**FIELD INSPECTION FORM**
 Loc ID 334942 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481533	SPILL OR RELEASE	AC	02/04/2022		-	Sales Line	EG

General Comment:
[Engineering Integrity Inspection performed on February 17, 2022; in response to Supplemental form 19-release report Doc # 402954101](#)

Inspected FacilitiesFacility ID: 481533 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Sales Line	1 of Lines	
----	------------------	------------	--

Flowline Description

Flowline Type: Sales Line Size: Material: Carbon Steel
 Variance: No Age: Contents: Natural Gas

Integrity Summary

Failures: External Corrosion Spills: Yes Repairs Made: No
 Coatings: H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Existing sales flowline was abandoned and removed from location

Appears to be external corrosion

New flowline to be installed a later date

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693201054	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5713098