

**Inspection Photos**  
**Operator: Logos Operating**  
**API: 067-09136**  
**Date: 3/21/2022**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of area where it appears that herbicide overspray has killed vegetation. Corrective action to revegetate areas where vegetation is killed from previous reclamation inspection is not addressed.




Photo 3. View of shrubs in the southeastern project area that appear to have been killed by herbicide overspray or soil contamination.



Photo 4. Another view of area in the southern project area (between access road and well pad, where vegetation is killed. Revegetation has not been conducted here. Topsoil scouring, pedestalling, and rilling observed.



Photo 5. View of the southern project area from the southeastern corner facing westward. Grasses in the foreground largely appear dead. Spot seeding is needed in areas with sparse and bare vegetation and where there is vegetation die-off.



Photo 6. View of open cellar around the wellhead needing cover for wildlife protection.



Photo 7. View of reference area comprised of sagebrush shrubland with understory of James galleta, squirreltail, prickly pear, and penstemon.