

Inspection Photos  
Operator: Amoco  
API: 385503  
Date: 3/21/2022




Photo 1. View of risers that remain within the former facilities area.




Photo 2. View of risers that remain around the wellhead marker.



Photo 3. View of cable debris that remains within the eastern project area.



Photo 4. View of riser east of the former well pad that appears to be no longer in use.



Photo 5. View of reference area comprised of sagebrush shrubland with understory of James galleta, squirreltail, prickly pear, and matte penstemon.