

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2022

Submitted Date:

03/29/2022

Document Number:

698100247**FIELD INSPECTION FORM**Loc ID 335365 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
,		COGCC.inspections@caerusoilandgas.com	All Inspections
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481823	SPILL OR RELEASE	AC	03/25/2022		-	P26NWB Dumpline Release	EI

General Comment:

[COGCC Environmental Inspection of Benzel \(P26NWB\) pad and dumpline release \(Spill/Release ID #481823\). Follow-up to Operator's Initial Spill/Release Report, doc #402994926.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment: Unlined secondary containment is not sufficiently impervious to contain spilled or released materials.				
Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure per Rule 603.o.(3).				Date: <u>05/28/2022</u>

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Other	Inadequate	39.491802	-107.737938
Comment:	Localized accumulations of oil-stained soil observed along flowpath, approximately 200' NW of tank battery. See photos.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Control runoff from stained soil area to prevent additional impacts to surface water.			Date: 03/30/2022

Spill/Remediation:

Comment:	Spill/Release Report doc #402994926 describes the release of produced water, paraffin, and condensate from a failed dumpline at the tank battery with surface water impacts to the stockpond located approximately 375' NW of the tank battery. Unidentified fluids observed in excavation area north of tank battery. See photos.			
Corrective Action:	Remove and properly dispose of fluids. Comply with Rules 912 and 913 for delineation and remediation of spills/releases.			Date: 03/30/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402997591	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706834
698100248	20220328 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5706833