

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC KEINATH-68S96W /4SENW**

**Location ID: 334387**



**Photo #6335 from entrance to location.**



**Photo #6335 No battery sign located at the tank battery.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH-68S96W /4SENW

Location ID: 334387



**Photo #6337** Location lacks stabilization.



**Photo #6338** Insufficient tracking control located at entrance to location.