

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2022

Submitted Date:

04/05/2022

Document Number:

693201052

FIELD INSPECTION FORM

Loc ID 322522 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		maralextech@gmail.com	all inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
		thahn@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210708	WELL	SI	01/11/1911	GW	045-06466	FEDERAL 19-1	SI

General Comment:

Engineering Integrity Inspection performed on March 30, 2022. In response to Form 42 Document number 402969225. To witness Flowline Abandonment.

Inspected Facilities

Facility ID: 210708 Type: WELL API Number: 045-06466 Status: SI Insp. Status: SI

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC inspector showed up to witness flowline abandonment on the date and time noted on form 42 document number 402969225.
 Gate was locked and no sign of work being performed. Contacted Maralex Staff and was informed work was delayed

Corrective Action: Update form 42 to correct date of Abandonment and supply gate combo to Western Integrity Inspector Via email

Date: 04/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693201057	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5714102