

Inspection Photos
Marie Gerhart 9 Spill
Facility ID: 481902



Photo 1 – Spill Location – Stained soils remain in-situ



Photo 2 – Spill location – Stained soils remain in-situ



Inspection Photos
Marie Gerhart 9 Spill
Facility ID: 481902



Photo 3 – Spill location relative to livestock pins



Photo 4 – Spill location relative to livestock pins



Inspection Photos
Marie Gerhart 9 Spill
Facility ID: 481902



Photo 5 – Spill location relative to Landowner road



Photo 6 – Spill location relative to Landowner out buildings

