

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2022

Submitted Date:

04/05/2022

Document Number:

693804404

FIELD INSPECTION FORMLoc ID 322318 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 22370

Name of Operator: D & G ROUSTABOUT SERVICE

Address: 765 S 1/2 ROAD

City: MACK State: CO Zip: 81525

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|----------------------------------|-----------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Terrell, David | 970-858-1581 | terrelloil@aol.com | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , | | dnr_cogccengineering@state.co.us | |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 210269 | WELL | SI | 01/01/2019 | GW | 045-06025 | WEST SALT CREEK-FEDERAL 1-7 | SI |

General Comment:

COGCC staff performed a routine field inspection on 4/4/2022.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

| Location | | | | |
|--|---|--------|-------|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective ActionL | | | Date: | |
| Type | Main | | | |
| comment: | | | | |
| Corrective ActionL | | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | CA from inspection doc#693802960 completed | | | |
| Corrective Action: | | | Date: | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | CA from inspection doc#693802960 completed | | | |
| Corrective Action: | | | Date: | |
| Emergency Contact Number: | | | | |
| Comment: | 970-858-1581 or 911 CA from inspection doc#693802960 completed | | | |
| Corrective Action: | | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Tube fence | | | |
| Corrective Action: | | | Date: | |
| Equipment: | | | | |
| | | | | corrective date |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Bradenhead | # 1 | | | |
| Comment: | CA from inspection doc#693802960 completed | | | |
| Corrective Action: | | | Date: | |

| | | | |
|--------------------------|-----|--|-------|
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|-----------|----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLs | Open Top | | 39.550869,-108.922952 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 210269 Type: WELL API Number: 045-06025 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shut in 12/1/2018. No MIT on record.Corrective Action: WARNING LETTER #402626448 sent 3/11/2021.

Date: 06/30/2021

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 693804415 | Inspection photos 4/4/2022 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5715152 |