

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2022

Submitted Date:

04/05/2022

Document Number:

696304103

**FIELD INSPECTION FORM**Loc ID 310566 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                           | Comment         |
|--------------|-------|---------------------------------|-----------------|
| ,            |       | regulatory@foundationenergy.com | All Inspections |
| Morgan, John |       | john.morgan@state.co.us         |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 293534      | WELL | SI     | 03/27/2017  | OW         | 123-26575 | GREEN 1-1     | SI          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                          |                                  |       |                 |
|--------------------------|----------------------------------|-------|-----------------|
|                          |                                  |       | corrective date |
| Type: Other              | # 1                              |       |                 |
| Comment:                 | Injection Wellhead               |       |                 |
| Corrective Action:       |                                  | Date: |                 |
| Type: Deadman # & Marked | # 4                              |       |                 |
| Comment:                 |                                  |       |                 |
| Corrective Action:       |                                  | Date: |                 |
| Type: Bradenhead         | # 1                              |       |                 |
| Comment:                 | Appears to be plumbed to surface |       |                 |
| Corrective Action:       |                                  | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 293534 Type: WELL API Number: 123-26575 Status: SI Insp. Status: SI**Underground Injection Control**UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: 4350UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 09/12/2019

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Annual UIC Inspection  
 Injection Pump NOT Injecting at time of Inspection  
 Tubing: 0 PSI  
 Unable to document Casing & Bradenhead pressures  
 Casing & Bradenhead had bullplugs installed, did NOT have pressure gauges  
 Last MIT: 09/12/2019  
 MAIP: 2250# H2O Injection  
 MAIP: 4400# Gas Injection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| Routine Annual UIC Field Inspection. NOT Injecting at the time of Inspection. Casing & Bradenhead had bullplugs installed, did NOT have pressure gauges. | petrie | 04/05/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696304104    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5715156">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5715156</a> |