

Inspection Photos
Operator: Simcoe
API: 067-07266
Date: 3/28/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with irrigated and non-irrigated grasses such as western wheatgrass, crested wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of irrigated grass field with smooth brome and western wheatgrass observed.