

Inspection Photos
Operator: Simcoe
API: 067-06330
Date: 3/28/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing here with dense rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of rubber rabbitbrush shrubland and grass field with grasses largely in a grazed vegetative condition at this time.