

Inspection Photos

4/04/2022

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 1: Photos taken from the soil stockpile on the Location; Operator has placed a straw wattle at base of stockpile; BMP has not been installed per good engineering practices, or maintained in a proper functioning condition. BMPs at stockpile remain inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 2: Photos taken from the soil stockpile on the Location; Operator has placed a straw wattle at base of stockpile; BMP has not been installed per good engineering practices, or maintained in a proper functioning condition. BMPs at stockpile remain inadequate.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 3: Photos show inadequate stabilization and tracking BMPs on the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 4: Photos show adequate, impervious containment has not been installed at the tanks in accordance with good engineering practices.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 5: Photos show adequate, impervious containment has not been installed at the tanks in accordance with good engineering practices.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324464



Photo 6: Photos taken from the interim areas on the north/northwest end of the Location. Equipment/Vehicles/Trash/Debris/etc.. previously being stored on interim areas have been removed. Limited visibility due to snow cover prevented Reclamation Specialist from conducting an accurate assessment of the interim areas; however, unable to find evidence that reclamation per Rule 1003.b has been conducted on areas not needed for production, and no “CA Complete” resolution has been submitted with documentation showing work was completed..