

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2022

Submitted Date:

04/06/2022

Document Number:

696203549

FIELD INSPECTION FORM

Loc ID 324475 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		geops@oxbow.com	
		Heather.Lang@oxbow.com	
Longworth, Mike		michael.longworth@state.co.us	
		Tyson.Johnston@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324475	LOCATION	AC			-	DGU Federal 1289 17-13 Pad	RI
436660	WELL	DG	09/01/2019	LO	051-06127	DGU Federal 1289 17-13 CS2	RI

General Comment:

On 4/4/2022 Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Gunnison Energy's DGU Federal 1289/17-13 pad location in Gunnison County, Colorado.

It was observed that the following corrective actions per inspection #701102291 (dated 12/1/2021) remain applicable:

- Tank battery sign missing information per Rule 605.e.. EMS# or 911, Nearest public road, API#, Legal description. Post 911 at battery sign by 1/3/2022.
- Well sign API # and legal description illegible.
- Heated separator has a glycol storage tank with no labeling.

Inspector included on report for notification purposes.

The following compliance issues were observed during this inspection:

- Reclamation of conductor

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Inspection #701102291 observed heated separator has a glycol storage tank with no labeling. Inspection required Operator to comply with Rule 605.h by 3/3/2022. Unable to find labeling at separator. CA Remains applicable.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	03/03/2022
Type	WELLHEAD		
Comment:	Inspection #701102291 observed illegible API # and legal description on well sign. Inspection required Operator to comply with Rule 605.d and 605.g by 3/3/2022. It was observed in this inspection that signage remains inadequate. CA Remains applicable.		
Corrective Action:	Install sign to comply with Rule 605.d. Install sign to comply with Rule 605.g.	Date:	03/03/2022
Type	BATTERY		
Comment:	Inspection #701102291 observed tank battery sign missing information per Rule 605.e.. EMS# or 911, Nearest public road, API#, Legal description. Inspection required Operator to comply with Rule 605.e by 3/3/2022. It was observed in this inspection that signage remains inadequate. CA Remains applicable.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	03/03/2022

Emergency Contact Number:

Comment: Inspection #701102291 observed telephone number for local emergency services (911 where available); not posted on tank battery sign. Inspection required Operator to comply with Rule 605.e by 1/3/2022.

It was observed in this inspection that signage remains inadequate. CA Remains applicable.

Corrective Action: Install sign to comply with Rule 605.e. by 1/3/2022

Date: 01/03/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 324475 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Facility ID: 436660 Type: WELL API Number: 051-06127 Status: DG Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment No waste or debris on observed on interm and production areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment No unused or unneeded equipment observed on interm and production areas of the Location.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment Anchors observed with required marking.

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment It was observed in this inspection that interim areas are progressing towards 1003 standards. No issues/concerns observed.

Continue to monitor and manage interim areas of the Location until the site receives a passing final inspection.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled **Fail** _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Form 2 Permit 401108881 for well API 051-06127 expired 12/21/2018. Form 4 #402834900 states the conductor was plugged and abandoned on 9/29/2020.

It was observed in this inspection that the conductor and cellar for well API 051-06127 remains, and has not been plugged and reclaimed in accordance with Rule 406.e requirements.

Corrective Action: **Comply with Rule 406.e.(4).**

Date **05/31/2022**

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203550	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5716059