

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2022

Submitted Date:

04/06/2022

Document Number:

702400284**FIELD INSPECTION FORM**Loc ID 311287 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240181	WELL	PR	05/01/2021	OW	123-07969	AMOCO ENERGY SMITS UNIT C 1	PR
476146	OFF-LOCATION FLOWLINE	AC	12/28/2020		-	Wellhead Line 28NWNW	AC
476147	OFF-LOCATION FLOWLINE	AC	12/28/2020		-	Wellhead Line 28NWNW	AC

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate, fading/peeling and will need to be replaced in the near future		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate, fading and will need to be replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:		appears plumbed to surface		Date:	
Corrective Action:				Date:	
Type:	Horizontal Heated Separator	# 1			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Gas Meter Run	# 1			
Comment:		no indication of calibration status, Calibrate gas metering equipment annually.		Date:	12/23/2021
Corrective Action:		Measure gas per Rule 430.		Date:	12/23/2021
Type:	Ancillary equipment	# 2			
Comment:		automation, electric panel, meter box and transformers		Date:	
Corrective Action:				Date:	
Type:	Prime Mover	# 1			
Comment:		electric motor		Date:	
Corrective Action:				Date:	
Type:	Flow Line	# 2			
Comment:				Date:	
Corrective Action:				Date:	
Type:	Bird Protectors	# 1			
Comment:				Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:		See Inspection Doc # 699304530 for related shared facilities and equipment.			
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 240181 Type: WELL API Number: 123-07969 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 10/27/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 476146 Type: OFF- API Number: - Status: AC Insp. Status: ACFacility ID: 476147 Type: OFF- API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 4/6/2022 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location: Amoco Energy Smits Unit C1</p> <p>API #05-123-07969.</p> <p>County: Weld.</p> <p>Location: Dry, Weather: partly cloudy and windy.</p> <p>While there, I observed a wellsite and tank battery, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues have been addressed:</p> <p>606 housekeeping: Dead thistle in TB berm has been cut and removed.</p> <p>1002..(2).D housekeeping: Stained soil observed in several spots on location has been cleaned and removed.</p> <p>During this inspection the following possible compliance issue was observed and is now delinquent:</p> <p>430 gas calibration: No indication of calibration status, CA date 12-23-2021.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	04/06/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400285	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5716373">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5716373</a>