

Inspection Photos  
Operator: Hilcorp  
API: 067-08671  
Date: 4/5/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from from the northwestern corner facing southward. Dense Russian thistle debris needs to be removed and properly disposed of.



Photo 3. View of water ponding within secondary containment. It appears ponding may be result of long-term slow leak from tank plumbing.



Photo 4. View of the southern project area from the southeastern corner facing westward.



Photo 5. View of reference area comprised of open grass field, with scattered rubber rabbitbrush and sagebrush shrubs, and western wheatgrass.