

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2022

Submitted Date:

04/07/2022

Document Number:

695106025

FIELD INSPECTION FORMLoc ID 309263 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290887	WELL	PR	06/04/2007	GW	071-09311	BLOSSOM 33-8	PR
300909	PIT	AC	05/05/2010		-	BLOSSOM 33-8	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5 & 6: AREA OF IMPACTED SOIL APPEARS TO BE OILY WASTE FROM PRIME MOVER SKID (NOTE: THE DRAIN PLUG IS MISSING AND OILY WASTE IS RUNNING ON THE GROUND. I SPOKE WITH ZEKE SANCHEZ TO RESOLVE ISSUE).		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. DISPOSE OF CONTAMINATED MATERIALS.	Date:	04/13/2022
Type	OTHER		
Comment:	PHOTO 4: PACKING ON DRIVEHEAD IS LEAKING (SPOKE WITH ZEKE SANCHEZ WITH EVERGREEN TO RESOLVE).		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905.	Date:	04/09/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	BRHD IS ACCESSABLE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 290887 Type: WELL API Number: 071-09311 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 11/14/2011Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 300909 Type: PIT API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [PHOTO 7: OILY WASTE IN PRIME MOVER SKID. COMPLY WITH RULE 1002.f.\(2\)B,](#)

Corrective Action: [Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.](#)

Date: 04/08/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 300909 Lat: 37.098060 Long: -104.582700

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	300909	1941796	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
695106026	INSP. PHOTOS	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717909