

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2022

Submitted Date:

04/07/2022

Document Number:

699603019

FIELD INSPECTION FORM

Loc ID 456482 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270375	WELL	PA	07/03/2019	GW	123-21882	HUCK 41-28	PA
435738	TANK BATTERY	AC	04/14/2009		-	Huck 41-28 PAD	PA
456482	LOCATION	AC	07/03/2019		-	Huck 41-28 Pad	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.376275 / -104.434113

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type		#			corrective date
Gas Meter Run		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Ancillary equipment		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Emission Control Device		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:
Horizontal Heated Separator		# 0			
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0					
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.					
Corrective Action:						Date:

Paint

Condition	<input type="text"/>
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	0						
Comment:		Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				Date:	
Corrective Action:						Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:						Date:	
Corrective Action:						Date:	

Venting:

Yes/No					Date:	
Comment:					Date:	
Corrective Action:					Date:	

Flaring:

Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 270375 Type: WELL API Number: 123-21882 Status: PA Insp. Status: PAFacility ID: 435738 Type: TANK API Number: - Status: AC Insp. Status: PAFacility ID: 456482 Type: LOCATION API Number: - Status: AC Insp. Status: PA**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 04/05/2022 at approximately 14:06 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: Huck /41-28 Pad Location ID: 456482 Well Name(s): Huck 41-28. API: 05-123-21882. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry, dusty. Visibility reduced because of gusty winds.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.376275 / -104.434113</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6S on file. Plugging, cut/cap date: 07/03/2019. Approved. Plugged & Abandoned PA well GPS coordinates: 40.375890 / -104.433470 Abaandoned Batt GPS coordinates: 40.376275 / -104.434113</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/07/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699603020	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717961