

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2022

Submitted Date:

04/01/2022

Document Number:

701004789

FIELD INSPECTION FORM

Loc ID 302995 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252233	WELL	PR	01/18/2018	GW	125-06102	WHOMBLE 1-6	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
	Type	Access	
	comment:	Two track through pasture	
	Corrective Action:		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
	Type	OTHER	
	Comment:	Lease sign for associated wells mounted to meter shed	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:	Lease sign by wellhead	
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
	Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 600px; height: 20px;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead, VGS and meter shed	
	Corrective Action:		Date:
Equipment:			
			corrective date
Type:	Gas Meter Run	# 5	
	Comment:	Shared meter run for (Whomble 1-6, 5-6, 8-6, 9-6 & Whomble 2-5)	
	Corrective Action:		Date:
Type:	Vertical Separator	# 5	
	Comment:	5-Vertical gas separators 50% buried by meter shed	
	Corrective Action:		Date:
Type:	Ancillary equipment	# 1	
	Comment:	Telemetry equipment	
	Corrective Action:		Date:
Venting:			
	Yes/No		
	Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 252233 Type: WELL API Number: 125-06102 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Whomble 1-6, 5-6, 8-6, 9-6 & 2-5\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Fail			

Comment: [Access has erosion near location and needs maintenance](#)

Corrective Action: [Repair access near erosion](#)

Date: 07/31/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403002423	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5712378
701004790	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5712373
701004791	Access erosion near location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5712374