

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2022

Submitted Date:

04/05/2022

Document Number:

693201053

FIELD INSPECTION FORMLoc ID 312449 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
	970-563-4000	maralextech@gmail.com	all inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
		thahn@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221634	WELL	TA	01/01/2021	GW	077-08236	LEE, RUBY-FEDERAL 2-32-8-101	EG

General Comment:

Engineering Integrity Inspection performed on March 30, 2022. In response to Form 42 Document number 402969303. To witness Flowline Abandonment

Inspected Facilities

Facility ID: 221634 Type: WELL API Number: 077-08236 Status: TA Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC inspector showed up to witness flowline abandonment on the date and time noted on form 42 document number 402969303.

Contacted Maralex Staff and was informed work was delayed

Corrective Action: Update form 42 to correct date of Abandonment Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403004340	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5714106
693201058	Photo 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5714103
693201059	Photo 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5714104