

Inspection Photos
Location Name: Federal-Chamberlin 22-1
Location ID: 312863



Photo 1. Overview of location taken facing southeast. Tubing stored at wellhead.



Inspection Photos
Location Name: Federal-Chamberlin 22-1
Location ID: 312863



Photo 3. Fired vessel less than 50 feet from crude tanks.



Photo 3. Stained soil at wellhead.