

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

702000156

FIELD INSPECTION FORMLoc ID 312970 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------|
| | | dnr_cogccengineering@state.co.us | |
| Evans, Clay | | antlerenergy@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 223077 | WELL | PR | 07/31/2003 | OW | 081-06439 | AMOCO-FEDERAL 21-1 | PR |

General Comment:

Routine follow up inspection. Follow up to inspection from 1/3/2022 document number 689806875 and 11/16/2020 document number 689804994. No corrective actions have been made. Compliance issues remaining:

- east tank missing label
- stained soil at pump jack
- no permit for one of two pits on location

Compliance issues observed during this inspection:

- apparent spill of diesel or lube oil at pump jack
- chemical container at entrance blown over and become debris, chemical container at wellhead without secondary containment

Location

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | East tank has no label. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 01/20/2021 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | DEBRIS | | |
| Comment: | Chemical container at entrance has blown over and become debris. Used absorbent pads observed blowing off location. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 04/26/2022 |
| Type | OTHER | | |
| Comment: | Stained soil at pump jack. | | |
| Corrective Action: | Comply with Rule 606 Properly dispose of oily waste in accordance with 905.e. | Date: | 05/12/2022 |

Overall Good: ☐

| | | | |
|--------------------|--|----------|------------------|
| Spills: | | | |
| Type | Area | Volume | |
| Lube Oil | Pump Jack | <= 1 bbl | |
| Comment: | Stained soil and free fluid from apparent spill of diesel or lube oil at pump jack. Absorbent pads had been placed but did not absorb all free fluid. No evidence of attempt to contain or remove impacted soil. Inspector spoke with pumpers in the field to inform them that spill needed to be immediately addressed. | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Contact COGCC EPS staff. Require appropriate cleanup. | | Date: 04/13/2022 |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----|-------|--|
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|------------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 2 | 400 BBLs | HEATED STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|-------|--|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|------------|
| Facility ID: | 223077 | Type: | WELL | API Number: | 081-06439 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement. | | | | | | | | |
| Corrective Action: | Submit required Form 7(s) to COGCC per rule 413. | | | | | | | Date: | 05/12/2022 |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement. Chemical container at wellhead stored without secondary containment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/26/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

| Type: | Lined: | Pit ID: | Lat: | Long: |
|------------------------|--------------|---------------|--------------|-------|
| Reference Point: _____ | Other: _____ | Length: _____ | Width: _____ | |

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: One pit on north side of location. One pit in tank battery. The COGCC database shows only 1 pit related with this well, 112982.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 908.a.

Date: 05/14/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 702000161 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721480 |