

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

688801148**FIELD INSPECTION FORM**Loc ID 333532 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		FarmingtonRegulatoryTechs@hilcorp.com	
Fischer, Alex		alex.fischer@state.co.us	
Killough, Mitch		mkillough@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262060	WELL	PR	08/20/2003	GW	067-08671	R&G 26-2	EI
424065	WELL	PR	12/02/2011	GW	067-09862	R&G 26-3	EI

**General Comment:**

On April 11, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company R&G #26-2. For the most recent field inspection report of this facility, please refer to document #693904377.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels are peeling off of tanks.		
Corrective Action:	Install signs to comply with Rule 605.h.	Date:	05/12/2022
Type	WELLHEAD		
Comment:	Free standing signs near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Perimeter fencing around well heads and pump jacks. Guard fencing present on both pump jacks.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric motors.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electrical supply equipment and electric pump controllers.		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	HEATED STEEL AST		37.071837,-107.573679	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined metal secondary containment ring. Previous inspection noted standing water inside the secondary containment. The operator inspected the ASTs and reported that the accumulated water was storm water.			
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
067-08671
067-09862

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>262060</u>	Type:	<u>WELL</u>	API Number:	<u>067-08671</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>424065</u>	Type:	<u>WELL</u>	API Number:	<u>067-09862</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
	hughesjo	04/12/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801149	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722032">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722032</a>