

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 1 Well head. Trash and unused equipment



Photo 2 Trash and unused equipment.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Colorado Oil and Gas Conservation Commission
39.85312, -104.26113, 1586.0m
Apr 12, 2022 12:09:14 PM

Photo 3 Mechanical issue and stained soil under and around gas powered motor.



Colorado Oil and Gas Conservation Commission
39.85317, -104.26106, 1589.0m
Apr 12, 2022 12:09:30 PM

Photo 4 Mechanical issue and stained soil under and around gas powered motor.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 5 Trash (PU belts)



Photo 6 Guy line anchors not properly marked. Dead weeds around location.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 7 Guy line anchors not properly marked. Dead weeds around location.

Photo 8 Guy line anchors not properly marked. Dead weeds around location.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 9 Guy line anchors not properly marked. Dead weeds around location.



Photo 10 Guy line anchors not properly marked. Dead weeds around location.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Colorado Oil and Gas Conservation Commission
39.84991, -104.26061, 1584.0m
Apr 12, 2022 12:19:28 PM



Colorado Oil and Gas Conservation Commission
39.84968, -104.25981, 1586.0m
Apr 12, 2022 12:20:43 PM

Photo 11 Facility Pic

Photo 12 Production equipment (Crypto mining equipment)

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Colorado Oil and Gas Conservation Commission
39.84986, -104.25985, 1585.0m
Apr 12, 2022 12:24:13 PM



Colorado Oil and Gas Conservation Commission
39.8499, -104.25966, 1589.0m
Apr 12, 2022 12:24:46 PM

Photo 13 meter house and crypto mining equipment

Photo 14 Facility pic.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 15 production equipment. Barb wire fence in disrepair.



Photo 16 2" piping not LOTO

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 17 Crude oil tank



Photo 18 Produced water vaults. There are two vaults and only signage for one tank. Secondary containment has eroded away and is Inadequate.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699





Photo 19 Meter calibration card is past annual inspection inside meter house.

Photo 20 chart on unconnected meter on inlet to meter house. Chart dated 2020

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 21 meter on inlet side to meter house



Photo 22 Piping to inlet of meter house and gas supply to generator. Meter tubing not connected.

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Colorado Oil and Gas Conservation Commission
39.84975, -104.25975, 1587.0m
Apr 12, 2022 12:54:37 PM



Colorado Oil and Gas Conservation Commission
39.84974, -104.25967, 1587.0m
Apr 12, 2022 12:54:53 PM

Photo 23 location piping

Photo 24 location piping

Inspection Photos
Location Name: Haugen #1-30
Location ID: 319699



Photo 25 Access road off county road in disrepair vehicles driving off road and in farmers field.