

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2022

Submitted Date:

04/13/2022

Document Number:

702000164

FIELD INSPECTION FORM

Loc ID 416425 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
		dnr_cogccenforcement@state.co.us	
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418294	WELL	SI	08/01/2020	GW	081-07616	JACKS DRAW 19	SI

General Comment:

Inspector on location to witness MIT. Casing could not hold pressure. Test was failed in the field.

Inspected Facilities

Facility ID: 418294 Type: WELL API Number: 081-07616 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT. Casing was pressured to 620 psi. At five minutes psi had dropped to 573 psi. At 7.5 minutes the casing has lost more than 10% of the starting pressure and test was failed. Operator asked to complete 15 minutes of time to see if the pressure ever stabilized. The pressure continued to drop and at 15 minutes was at 514 psi. Operator agreed test was failed.

Corrective Action: **Repair and successfully retest or plug and abandon per Rule 417.f.** Date: 10/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702000165	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5723139