

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2022

Submitted Date:

04/07/2022

Document Number:

702400298**FIELD INSPECTION FORM**Loc ID 317912 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10528

Name of Operator: ARCH OIL & GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Jeff	940-391-7210	jbrowning@matthewssouthwest.com	All inspections
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240164	WELL	PR	03/01/2020	OW	123-07952	KAUFMAN 4	PR

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Debris(dead weeds) all along access rd		
Corrective Action	L Comply with Rule 606		Date: 12/16/2021
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign information inaccurate at well and has old operator information, Form 10(CO)(CC) Doc # 402470697 was approved on 10-8-2021.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 01/25/2022
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds around PJ fencing and WH		
Corrective Action:	Comply with Rule 606		Date: 03/02/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	gas engine		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Gas cylander for gas engine		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	

Comment: [See Inspection Doc # 702400296 for related shared facilities and equipment.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 240164 Type: WELL API Number: 123-07952 Status: PR Insp. Status: PR**Producing Well**Comment: [PR](#)

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/15/2019Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: [Submit Test results to the COGCC](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 4/7/2022 at approximately 1250 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to inspection Doc # 699304572.</p> <p>Operator: Arch Oil & Gas</p> <p>Location: Kaufman #4</p> <p>API #05-123-07952</p> <p>County: Weld.</p> <p>While there, I observed a wellsite, PR at the time of inspection.</p> <p>During this inspection the following possible compliance issues were observed and are now delinquent:</p> <p>605.d signs: WH sign has old operator information and needs to b updates, CA date 3-2-2022.</p> <p>606 housekeeping: Dead weeds along access rd. and around the well site. CA date 12-16-2021.</p> <p>See attached photos.</p> <p>Location: dry, Weather: cloudy and windy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	04/07/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403008514	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717966
702400299	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5717964