

| | | | | | | |
|-------------------|---|------------------|-----------------------|------------|----------------------|-------|
| Today's Date: | 3/29/2022 | | | | | |
| Well Name: | FLORIDA RIVER ESTATES 33-09-20 1 | Location: | Sec: 20 | Twn: 033N | Rng: 009W | UL: C |
| API Number: | 05.067.08167 | Footage: | 1315' FNL & 1535' FWL | | | |
| Operator: | Hilcorp Energy Company | Area/Run/MSO: | 01 | 0105 | Pepe Frias Hernandez | |
| Meter #: | 06633073 | | Pipeline: | HEC | | |
| | | | | | | |
| INC Number: | 688801126 | Agency: | COGCC | Inspector: | Jim Hughes | |
| Type of INC: | Written | Photos Required: | Yes | Due Date: | 4/29/2022 | |
| Issue of Concern: | <p>On March 24, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Company Florida River Estates 33-9 #20-1. For the most recent field inspection report of this facility, please refer to document #693902376.</p> <p>During this inspection staining was observed on and around the #20-1 well head. Well head and surrounding gravel are stained at the #20-1.</p> <p>Control and contain spills/releases and clean up per Rule 912.a.</p> | | | | | |

From: Ashton Hemphill <ahemphill@hilcorp.com>

Sent: Thursday, April 14, 2022 4:50 AM

To: Tammy Jones <tajones@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>

Subject: RE: FLORIDA RIVER ESTATES 33-09-20 1 - INC - 06633073

Operator cleaned the wellhead and impacted soil on the ground, he also treated with simple Green and raked it in.





