

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 3 TB sign.



Photo 4 TB tank volume faded

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 5 Ancillary equip..



Photo 6 Pump jack

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 7 Horiz. Heated Sep.



**Photo 8 Stained soil has been cleaned up from initial insp.
But the leak is still dripping.**

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 9 Slow leaking gasket on Horiz. Heated Sep.



Photo 10 Stained soil has been cleaned up around flow line manifold.

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 11 Horizontal Sep. stained soil in housing



Photo 1 Horizontal Sep. stained soil in housing

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 13 Gas Meter Run



Photo 14 Gas Meter Run

Inspection Photos
Location Name: Alfred Herman unit1
Location ID: 332917



Photo 15 sink hole south of Separator house

Photo 16 sink hole south of Separator house