

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2022

Submitted Date:

04/08/2022

Document Number:

689501365

FIELD INSPECTION FORMLoc ID 454141 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Spills&Remediations		COGCCSpillRemediation@pdce.com	
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481624	SPILL OR RELEASE	CL	02/25/2022		-	Boulter 15-26 Tank Battery	EI
481638	SPILL OR RELEASE	CL	02/25/2022		-	Boutler 15-21 - Separator	EI

General Comment:

This is an environmental inspection of Remediation Spill ID 481624 (CL) & 481638 (CL)/Remediation Project No 21306. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Soil berms and orange construction fencing was in place around the open excavation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities							
Facility ID:	<u>481624</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>
Facility ID:	<u>481638</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: At the time of inspection an excavation was open for spill remediation between the location of the former separator and ASTs (approx. size 100' x 50' x 20'). Piping was observed sticking out from the sidewalls of the excavation and portions of the sidewalls appeared to be collapsed in. No groundwater was observed in the open excavation.

Corrective Action: Submit an updated Supplemental Form 27 (Rem No 21306) for the remediation of this release.

Date: 05/06/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403009093	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5718444
689501366	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5718438