



**Inspection Photos**  
**Location Name: Two Mile Creek 22-13H**  
**Location ID: 422116**



**Photo 1 - Wellhead – Stained Soil**

**Photo 2 – Wellhead – Tubing Valves appear to be Closed Position**

**Inspection Photos**  
**Location Name: Two Mile Creek 22-13H**  
**Location ID: 422116**



Colorado Oil and Gas Conservation Commission  
40.90993, -103.74313, 4913.6ft, 70°  
04/14/2022 12:45:04



Colorado Oil and Gas Conservation Commission  
40.91055, -103.74313, 4903.5ft, 156°  
04/14/2022 12:43:30

**Photo 3 – Tank Battery Sign**

**Photo 4 – Stained Soil at Gas Engine Exhaust has been mitigated**