

Caerus Piceance LLC
J18
Location # 334865



Location/ lack of battery signage



location

Caerus Piceance LLC
J18
Location # 334865



Location



Open pipe

Caerus Piceance LLC
J18
Location # 334865



Lack of stabilization/ compaction/ erosion




Lack of stabilization/ compaction/ erosion

Caerus Piceance LLC
J18
Location # 334865



Sediment piled up on battery containment



Lack of cap/plug

Caerus Piceance LLC
J18
Location # 334865



Lack of stabilization/compaction



Lack of stabilization/compaction