

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2022

Submitted Date:

04/15/2022

Document Number:

700704100

FIELD INSPECTION FORMLoc ID 334933 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256551	WELL	PR	03/26/2004	GW	045-07470	HMU FEDERAL 18-15 (N18)	PR
256552	WELL	PR	01/04/2000	GW	045-07472	HMR FEDERAL 18-11 (N18)	PR
256553	WELL	PR	10/25/2001	GW	045-07471	HMR FEDERAL 18-14 (N18)	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 4/15/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus N18, at Location # 334933 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Some of the location shows signs of lack of stabilization/ compaction/ degradation.
2. Lack of battery signage.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	07/08/2022
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:		
Corrective Action:		Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in metal containment		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities			
Facility ID: 256551	Type: WELL	API Number: 045-07470	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 256552	Type: WELL	API Number: 045-07472	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
Facility ID: 256553	Type: WELL	API Number: 045-07471	Status: PR Insp. Status: PR
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [1. Some of the location shows signs of lack of stabilization/ compaction/ degradation.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 06/03/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704114	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725285