

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2022

Submitted Date:

04/15/2022

Document Number:

700704104

FIELD INSPECTION FORMLoc ID 334679 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285591	WELL	PR	07/12/2007	GW	045-12529	COUEY 23-16B (H23W)	PR
285592	WELL	PR	06/30/2007	GW	045-12528	COUEY 23-9 (H23W)	PR
285593	WELL	PR	07/07/2007	GW	045-12527	COUEY 23-8C (H23W)	PR
285597	WELL	PR	07/10/2007	GW	045-12526	COUEY FEDERAL 23-10 (H23W)	PR
292241	WELL	SI	10/01/2021	GW	045-14656	COUEY 24-5 (H23W)	SI
292242	WELL	PR	05/04/2008	GW	045-14655	COUEY 24-5C (H23W)	PR
292243	WELL	SI	01/01/2022	GW	045-14654	COUEY 24-12 (H23W)	SI
292262	WELL	PR	04/23/2008	GW	045-14658	COUEY 24-4D (H23W)	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 4/15/2022 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus H23W, at Location # 334679 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Some of the access and location shows signs of lack of stabilization/ compaction/ degradation.
2. Valve on tank missing cap/plug.
3. Lack of battery signage.
4. Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	See storm water		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Provide proper signage		Date: 07/08/2022
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended piping for thawing out dump lines on tanks and separators with exhaust from trucks.		
Corrective Action:	Eliminate possibility of wildlife to enter open lines for thawing out dump lines with exhaust from trucks.		Date: 04/29/2022
Type	OTHER		
Comment:	Valve on tank missing cap/plug.		
Corrective Action:	Install cap/plug		Date: 06/03/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 8		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities				
Facility ID: 285591	Type: WELL	API Number: 045-12529	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285592	Type: WELL	API Number: 045-12528	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285593	Type: WELL	API Number: 045-12527	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285597	Type: WELL	API Number: 045-12526	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 292241	Type: WELL	API Number: 045-14656	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced 9/2021				
Corrective Action:			Date:	
Facility ID: 292242	Type: WELL	API Number: 045-14655	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 292243	Type: WELL	API Number: 045-14654	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced 12/2021				
Corrective Action:			Date:	
Facility ID: 292262	Type: WELL	API Number: 045-14658	Status: PR	Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
Compaction	Fail					

Comment: [1. Some of the access and location shows signs of lack of stabilization/ compaction/ degradation.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 06/03/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704113	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725290