

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2022

Submitted Date:

04/15/2022

Document Number:

699804378

**FIELD INSPECTION FORM**

Loc ID 335143 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261849	WELL	PR	02/13/2002	GW	045-07986	PA 32-33	PR
286894	WELL	PR	09/21/2006	GW	045-12798	PA 322-33	PR
286895	WELL	PR	09/21/2006	GW	045-12797	PA 22-33	PR
286896	WELL	PR	02/13/2007	GW	045-12796	PA 422-33	PR

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 4/12/22 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PA66S95W /33SWNE. Location #335143 in Garfield County Colorado.  
Refer to document #699803918 inspection conducted on 12/27/22. Previous corrective actions have been completed. While there, I observed normal production operations. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>261849</u>	Type:	<u>WELL</u>	API Number:	<u>045-07986</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:									
Corrective Action:								Date:	
Facility ID:	<u>286894</u>	Type:	<u>WELL</u>	API Number:	<u>045-12798</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	<u>286895</u>	Type:	<u>WELL</u>	API Number:	<u>045-12797</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:								Date:	
Facility ID:	<u>286896</u>	Type:	<u>WELL</u>	API Number:	<u>045-12796</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						
		Ditches				
		Compaction				
Culverts						
Sediment Traps						
		Sediment Traps				
		Berms				
Berms						
		Gravel				

Comment: Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer Storm water for comments.</a>	depaoloc	04/15/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804379	Photos for Insp. #699804378	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725277">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725277</a>