

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2022

Submitted Date:

04/15/2022

Document Number:

690102977

**FIELD INSPECTION FORM**

Loc ID 335792 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1001 17TH STREET #2000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@gwogco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266810	WELL	TA	02/22/2021	GW	001-09466	CENTRICOM STATE 11-16	PA
300326	WELL	TA	02/08/2019	OW	001-09683	PARTERRE 25-16	PA
300327	WELL	TA	02/22/2021	OW	001-09684	PARTERRE 23-16	PA
300328	WELL	PA	10/01/2020	OW	001-09685	PARTERRE 13-16	PA
300329	WELL	TA	02/08/2019	OW	001-09686	PARTERRE 12-16	PA
300330	WELL	TA	02/08/2019	OW	001-09687	PARTERRE 22-16	PA
300331	WELL	TA	02/08/2019	OW	001-09688	PARTERRE 14-16	PA
300332	WELL	TA	02/08/2019	OW	001-09689	PARTERRE 11-16	PA
335792	LOCATION	AC			-	CENTRICOM STATE-61S67W 16NESW	EG

**General Comment:**

[COGCC Engineering Integrity Inspection; Flowline Removal Confirmation Photos uploaded](#)

Inspected Facilities									
Facility ID:	266810	Type:	WELL	API Number:	001-09466	Status:	TA	Insp. Status:	PA
Facility ID:	300326	Type:	WELL	API Number:	001-09683	Status:	TA	Insp. Status:	PA
Facility ID:	300327	Type:	WELL	API Number:	001-09684	Status:	TA	Insp. Status:	PA
Facility ID:	300328	Type:	WELL	API Number:	001-09685	Status:	PA	Insp. Status:	PA
Facility ID:	300329	Type:	WELL	API Number:	001-09686	Status:	TA	Insp. Status:	PA
Facility ID:	300330	Type:	WELL	API Number:	001-09687	Status:	TA	Insp. Status:	PA
Facility ID:	300331	Type:	WELL	API Number:	001-09688	Status:	TA	Insp. Status:	PA
Facility ID:	300332	Type:	WELL	API Number:	001-09689	Status:	TA	Insp. Status:	PA

Flowline			
#1	Type: Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Well Site	Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed:		Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
Comment:	All (8) wells on location have been plugged and abandoned; cut and cap operations have been completed. On location wellhead flowlines (all wells) have been removed; on location dump and process flowlines at facility/ battery (ID #335792) have been removed. No flowline risers were observed at the (PA) wellheads or facility/ battery (decommissioned/ tanks and equipment removed) areas during this field inspection.		
Corrective Action:			Date:
Facility ID:	335792	Type:	LOCATION
API Number:	-	Status:	AC
Insp. Status:	EG		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102979	Location signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725340">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725340</a>

690102980	PA wellheads; cut and cap completed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725341">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725341</a>
690102981	View of location; looking SW	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725342">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725342</a>