

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/18/2022

Submitted Date:

04/18/2022

Document Number:

693507036

FIELD INSPECTION FORM
 Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL & GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-----------------------------|-------------------------------|------------------|
| Bonanza, Creston | Extraction, Axis, Highpoint | Inspections@civiresources.com | All Inspections. |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 456736 | WELL | DG | 09/25/2019 | OW | 014-20759 | INTERCHANGE A S22-30-13C | DG |

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|-----------------|-------|--|
| Type | DRILLING/RECOMP | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------------------------|-------|--|
| Type | LOCATION | | |
| Comment: | Sound walls all four sides | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 456736 Type: WELL API Number: 014-20759 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Ensign 769 Pusher/Rig Manager: Danny Herrera
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: At time of inspection crew was rigging down and moving to the Interchange B pad.

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|----------------------------|---------|------------|
| <u>Routine inspeciton.</u> | silverr | 04/18/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693507037 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5726348 |