

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: SOUND WALL SECTIONS ON TR WELL PRIME MOVER HAVE BROKE AND SOME OF THEM APPEAR TO BE UNUSABLE. PHOTO 6: SOUND WALL SECTIONS ON TR WELL PRIME MOVER HAVE BROKE AND SOME OF THEM APPEAR TO BE UNUSABLE.		
Corrective Action:	REMOVE UNUSED EQUIPMNET PER RULE 606.	Date:	05/12/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	BOTH BRHD'S ARE ACCESSABLE		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	ON TR WELL		
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 286325 Type: WELL API Number: 071-08945 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/26/2011 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 286327 Type: WELL API Number: 071-08944 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/19/2017 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: PHOTO 7: 2ND CULVERT FROM WILDERNESS RIDGE ROAD ON LOCATION ROW IS PARTIALLY BLOCKED AT THE INLET NOTE: EVERY CULVERT ON THIS ROW IS IN THE SAME CONDITION EXCEPT THE 1ST CULVERT FROM LOCATION. PHOTO 8: 3RD CULVERT FROM WILDERNESS RIDGE ROAD ON LOCATION ROW IS PARTIALLY BLOCKED AT THE INLET NOTE: THIS CULVERT IS COMPLETELY COVERED.

Corrective Action: COMPLY WITH RULE 1002 SERIES RULES REGARDING BMP'S MAINTENANCE. CULVERT CA'S FROM PREVIOUS INSPECTION HAVE NOT BEEN ADDRESSED. IMMEDIATE ACTION IS REQUIRED.

Date: 04/12/2022

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695104386, NOT ALL CA'S HAVE BEEN ADDRESSED. THE CA FOR CLEANING CULVERTS IS THE SECOND NOTICE.	beardslt	04/12/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403014237	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722672
695106048	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5722657