

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2022

Submitted Date:

04/13/2022

Document Number:

702000164**FIELD INSPECTION FORM**Loc ID 416425 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccenforcement@state.co.us	
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418294	WELL	SI	08/01/2020	GW	081-07616	JACKS DRAW 19	SI

General Comment:

Inspector on location to witness MIT. Casing could not hold pressure. Test was failed in the field.

Inspected FacilitiesFacility ID: 418294 Type: WELL API Number: 081-07616 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT. Casing was pressured to 620 psi. At five minutes psi had dropped to 573 psi. At 7.5 minutes the casing has lost more than 10% of the starting pressure and test was failed. Operator asked to complete 15 minutes of time to see if the pressure ever stabilized. The pressure continued to drop and at 15 minutes was at 514 psi. Operator agreed test was failed.

Corrective Action: Repair and successfully retest or plug and abandon per Rule 417.f.Date: 10/13/2022**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403014794	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5723143
702000165	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5723139