

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2022

Submitted Date:

04/20/2022

Document Number:

690102984

FIELD INSPECTION FORM

Loc ID 327571 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247081	WELL	SI		GW	123-14878	PTF C 32-1	SI
247082	WELL	SI	09/01/2017	GW	123-14879	PTF C 32-8	SI

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection Photos Uploaded](#)

Inspected Facilities

Facility ID: 247081 Type: WELL API Number: 123-14878 Status: SI Insp. Status: SI

Facility ID: 247082 Type: WELL API Number: 123-14879 Status: SI Insp. Status: SI

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Wells (PTF C 32-1, PTF C 32-8) are SI. Battery services (2) wells as listed above; Signage at battery indicates long term shut in of location. OOSLAT (locks and tags) observed on off location flowline endpoints on valves at wellheads and inlet to production equipment (heated horizontal separator/ flowline manifold). The GMR is shut in. No Noble Energy personnel were on location at the time of this field inspection.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102990	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5728619
690102991	Flowline manifold at HHS; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5728620
690102992	PTF C 32-8 SI WH; OOSLAT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5728621