

Inspection Photos

API: 071-08113

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 1. Facing southwest along the main road near the electric gate. There has been roadbase applied to this area of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 2. This culvert along the main road is partially washed out and needs to be repaired. Lat/Long:37.08136,-104.62910. This has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 3. Further along the road the culvert outlet was repaired and rock outlet protection was installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 4. The road side has been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 5. Further west along the access road. This area has been repaired. There are rock check dams installed however they are small and may not hold up very well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 6. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022

Inspection Photos



Photo 7. Facing toward the pit. Water level has been lowered. The pit is shallow <2 ft. deep and needs to be constructed to allow 2 ft. freeboard. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08113 | Date: 4/19/2022