

# Inspection Photos

API: 071-07085

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/19/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07085 | Date: 4/19/2022

## Inspection Photos



**Photo 1.** Facing south toward the access road stream crossing. There is no bank stabilization at the outlet side.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07085 | Date: 4/19/2022



## Inspection Photos



**Photo 2.** There are two culverts installed at the stream crossing. This appears to be inadequate as the prior cement culvert shown in the photo on the right had 3 large culverts.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Facing northwest along the side of the access road. All disturbed areas along the road side need to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07085 | Date: 4/19/2022

## Inspection Photos



**Photo 5.** Facing southeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07085 | Date: 4/19/2022