

Inspection Photos
Operator: Simcoe
API: 067-06329
Date: 4/19/2022



Photo 1. View of the project area from well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass and rubber rabbitbrush.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of sagebrush shrubland with and understory of James galleta, western wheatgrass, purplethreewain, yellow milkvetch, and Indian paintbrush.