

Inspection Photos
Operator: Rim Operating
API: 067-08071
Date: 4/19/2022



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing largely with western wheatgrass rubber rabbitbrush, and purple threeawn.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised of sagebrush shrubland with and understory of James galleta, western wheatgrass, purplethreawn, yellow milkvetch, and Indian paintbrush.